

F-5-52

C.1880

Monrovia Bank
Monrovia
Private

The Monrovia Bank with its recessed brick work, decorative brackets supporting the slate roof and curved scrolls on the roof line make the building the most architecturally significant building in the town of Monrovia.

The bank operated between 1880 and 1920 until the decline of the B&O Railroad which once serviced the area.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC Monrovia Bank

AND/OR COMMON

2 LOCATION

STREET & NUMBER

North Side Rte 75

Sixth

CITY, TOWN

Monrovia

— VICINITY OF

CONGRESSIONAL DISTRICT
Frederick

STATE

Maryland

COUNTY

3 CLASSIFICATION

CATEGORY

—DISTRICT
☒ BUILDING(S)
—STRUCTURE
—SITE
—OBJECT

OWNERSHIP

—PUBLIC
☒ PRIVATE
—BOTH

PUBLIC ACQUISITION

—IN PROCESS
—BEING CONSIDERED

STATUS

☒ OCCUPIED
—UNOCCUPIED
—WORK IN PROGRESS
ACCESSIBLE
—YES: RESTRICTED
—YES: UNRESTRICTED
—NO

PRESENT USE

—AGRICULTURE —MUSEUM
☒ COMMERCIAL —PARK
—EDUCATIONAL —PRIVATE RESIDENCE
—ENTERTAINMENT —RELIGIOUS
—GOVERNMENT —SCIENTIFIC
—INDUSTRIAL —TRANSPORTATION
—MILITARY —OTHER

4 OWNER OF PROPERTY

NAME

Interstate Enterprises Inc.

Telephone #:

STREET & NUMBER

P.O. Box 18

Md. 21774

CITY, TOWN

New Market

— VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC.

Liber #: 877

Folio #: 90

STREET & NUMBER

CITY, TOWN

STATE

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

—FEDERAL —STATE —COUNTY —LOCAL

DEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION**CONDITION**

☒ EXCELLENT ☐ DETERIORATED
☐ GOOD ☐ RUINS
☐ FAIR ☐ UNEXPOSED

CHECK ONE

☐ UNALTERED
☒ ALTERED

CHECK ONE

☒ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Monrovia Bank is a one story square hipped roof brick structure laid in common bond which faces south from the east side of Route 75 (Green Valley Road) in Monrovia. The building is three bays wide on each side. The original main entrance is located in the southeast corner of the building; it is twin doors, with a two light transom. The present door is located in the north east corner of the building. Located in the remaining bays on the south and east sides are double hung 1/1 windows with a arched double hung 1/1 windows with two light transoms, and header arches. Each window has a carved wood inset below the arch. Each bay on the south and east side is separated by recessed brick work. The hip roof is replaced asphalt and is connected to the main structure by a boxed cornice with a dentiled brick frieze. Brackets support the roof in the southeast corner. On the top of the structure is a series of decorative carved scrolls which are most unusual.

The entire structure is in excellent condition and is currently being used as an office.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

PERIOD		AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION	
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE	
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE	
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN	
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER	
<input checked="" type="checkbox"/> 1800-1899	<input checked="" type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION	
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)	
		<input type="checkbox"/> INVENTION			

SPECIFIC DATES	BUILDER/ARCHITECT
----------------	-------------------

STATEMENT OF SIGNIFICANCE

Built after 1873 since it does not appear on the Titus Atlas of Monrovia, the Monrovia Bank served this community until the early nineteenth century and met its decline with the decline of the Railroad.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Cherilyn Widell

ORGANIZATION

Frederick County Office of Historic Preservation

DATE

STREET & NUMBER

Winchester Hall

TELEPHONE

694- 1063

CITY OR TOWN

Frederick

STATE

Md


The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

5562 1 NW
(LIBERTYTOWN)

5562 1 NW
(LIBERTYTOWN)





F-5-52 Monrovia Bank
E/s Rte 75
Monrovia

CEW 5/78